



PUMPCOAT

THE RIGHT SOLUTION TO YOUR PUMP AND COATING PROBLEMS



CASE HISTORY 012 - BOILER FEED PUMP

1) **Problem:**

Industrial power plant in the northeast was experiencing premature wear of steel casing.

2) **Circumstances prior to failure:**

Customer experienced washout of casing at area behind throttle bushing and center bushing.

3) **Pumpcoat Solution**

Pumpcoat provided casing repair and modification of throttle bushing and center Bushing by adding AFLAS O-Rings.

OUR MISSION IS TO PROVIDE HIGHLY TECHNICAL AND
RELIABLE SERVICE THROUGH OUR ESTABLISHED NETWORK
OF AFFILIATED VENDORS AND STRATEGIC PARTNERS.

Pumpcoat, Inc.

PO Box 1109

Mashpee, MA 02649

sales@pumpcoat.com

www.pumpcoat.com

1-888-312-7278 (toll-free)

1-508-540-5878 (phone)

1-508-457-1052 (fax)

~ WBE Certified ~