

PUMPCOAT

THE RIGHT SOLUTION TO YOUR PUMP AND COATING PROBLEMS



CASE HISTORY 014 - FLY ASH VALVE ACTUATOR PARTS

1) **Problem:**

Customer unhappy with quality and price of frequently used valve parts.

2) **Circumstances prior to failure:**

Parts were received needing modifications to fit worn tertiary ash system.

3) **Pumpcoat Solution**

Pumpcoat worked with the customer to print out and supply fitted valve parts sets. This allowed mechanics to reduce time when installing replacement parts.

OUR MISSION IS TO PROVIDE HIGHLY TECHNICAL AND
RELIABLE SERVICE THROUGH OUR ESTABLISHED NETWORK
OF AFFILIATED VENDORS AND STRATEGIC PARTNERS.

Pumpcoat, Inc.

PO Box 1109

Mashpee, MA 02649

sales@pumpcoat.com

www.pumpcoat.com

1-888-312-7278 (toll-free)

1-508-540-5878 (phone)

1-508-457-1052 (fax)

~ WBE Certified ~