

# PUMPCOAT

## THE RIGHT SOLUTION TO YOUR PUMP AND COATING PROBLEMS



### CASE HISTORY 018 - COAL PULVERIZING WEAR PLATE

1) **Problem:**

Wear plates exhibited high rates of wear at irregular areas

2) **Circumstances prior to failure:**

Customer wanted more life from pulverizer wear plates. Irregular areas, sharp corners, and bolt hole areas experienced high wear rates

3) **Pumpcoat Solution**

Pumpcoat contractors applied Zirconium filled epoxy to extend wear plate life

OUR MISSION IS TO PROVIDE HIGHLY TECHNICAL AND  
RELIABLE SERVICE THROUGH OUR ESTABLISHED NETWORK  
OF AFFILIATED VENDORS AND STRATEGIC PARTNERS.

### Pumpcoat, Inc.

PO Box 1109

Mashpee, MA 02649

[sales@pumpcoat.com](mailto:sales@pumpcoat.com)

[www.pumpcoat.com](http://www.pumpcoat.com)

1-888-312-7278 (toll-free)

1-508-540-5878 (phone)

1-508-457-1052 (fax)

~ WBE Certified ~