



PUMPCOAT

THE RIGHT SOLUTION TO YOUR PUMP AND COATING PROBLEMS



CASE HISTORY 019 - PAINT OIL COOLERS

1) **Problem:**

Wear plates exhibited high rates of wear at irregular areas

2) **Circumstances prior to failure:**

Customer wanted more life from pulverizer wear plates. Irregular areas, sharp corners, and bolt hole areas experienced high wear rates

3) **Pumpcoat Solution**

Pumpcoat contractors applied Zirconium filled epoxy to extend wear plate life

OUR MISSION IS TO PROVIDE HIGHLY TECHNICAL AND
RELIABLE SERVICE THROUGH OUR ESTABLISHED NETWORK
OF AFFILIATED VENDORS AND STRATEGIC PARTNERS.

Pumpcoat, Inc.

PO Box 1109

Mashpee, MA 02649

sales@pumpcoat.com

www.pumpcoat.com

1-888-312-7278 (toll-free)

1-508-540-5878 (phone)

1-508-457-1052 (fax)

~ WBE Certified ~