

PUMPCOAT

THE RIGHT SOLUTION TO YOUR PUMP AND COATING PROBLEMS



CASE HISTORY 021 - FILTER HOUSING

1) Problem:

Customer needed replacement salt water filter housing.

2) Circumstances prior to failure:

Part was not in stock room, OEM replacement cast part was long lead time and expensive.

3) Pumpcoat Solution

Pumpcoat contracted a vendor to fabricate and machine a replacement part of carbon steel. We coated the unit with epoxy in our shop. The customer saved money and the lead time was reduced to two weeks.

OUR MISSION IS TO PROVIDE HIGHLY TECHNICAL AND
RELIABLE SERVICE THROUGH OUR ESTABLISHED NETWORK
OF AFFILIATED VENDORS AND STRATEGIC PARTNERS.

Pumpcoat, Inc.

PO Box 1109

Mashpee, MA 02649

sales@pumpcoat.com

www.pumpcoat.com

1-888-312-7278 (toll-free)

1-508-540-5878 (phone)

1-508-457-1052 (fax)

~ WBE Certified ~