



PUMPCOAT

THE RIGHT SOLUTION TO YOUR PUMP AND COATING PROBLEMS



CASE HISTORY 022 - HIGH FLOW PUMP

1) Problem:

Customer needed replacement salt water pump.

2) Circumstances prior to failure:

Customer salt water pump was 40 years old.
Customer decided to order a new pump which would fit into existing pump location.

3) Pumpcoat Solution

Pumpcoat worked with Ruhrpumpen to design a 316 SS pump with 2 % Nickel cast iron head which bolted in and duplicated existing pump hydraulics.
The new pump was designed so that the Nitronics 50 line shaft couplings were interchangeable with the customers existing pumps to reduce inventory.

OUR MISSION IS TO PROVIDE HIGHLY TECHNICAL AND
RELIABLE SERVICE THROUGH OUR ESTABLISHED NETWORK
OF AFFILIATED VENDORS AND STRATEGIC PARTNERS.

Pumpcoat, Inc.

PO Box 1109

Mashpee, MA 02649

sales@pumpcoat.com

www.pumpcoat.com

1-888-312-7278 (toll-free)

1-508-540-5878 (phone)

1-508-457-1052 (fax)

~ WBE Certified ~