



# PUMPCOAT

## THE RIGHT SOLUTION TO YOUR PUMP AND COATING PROBLEMS

### CASE HISTORY 027 - CONDENSER WATER BOX REPAIR



1) **Problem:**

Customer had hole in condenser water box.

2) **Circumstances prior to failure:**

Corrosion weakened the metal and customer needle-gunned a hole in condenser water box.

3) **Pumpcoat Solution**

Pumpcoat coating technician repaired hole by grit blasting, applying paste grade epoxy to fill the corroded area, and then a top coat to seal and waterproof. Patch was reinforced with polyester cloth. Patch has been working for 5 years.

OUR MISSION IS TO PROVIDE HIGHLY TECHNICAL AND  
RELIABLE SERVICE THROUGH OUR ESTABLISHED NETWORK  
OF AFFILIATED VENDORS AND STRATEGIC PARTNERS.

### Pumpcoat, Inc.

PO Box 1109

Mashpee, MA 02649

[sales@pumpcoat.com](mailto:sales@pumpcoat.com)

[www.pumpcoat.com](http://www.pumpcoat.com)

1-888-312-7278 (toll-free)

1-508-540-5878 (phone)

1-508-457-1052 (fax)

~ WBE Certified ~