



# PUMPCOAT

## THE RIGHT SOLUTION TO YOUR PUMP AND COATING PROBLEMS

### CASE HISTORY 005 - DEMIN TANK LINING



1) **Problem:**

Power plant in New England needed to replace tank lining on demin tank which was 12 years old.

2) **Circumstances prior to failure:**

Coating had bubbled but not failed.

3) **Pumpcoat Solution**

Our coating specialists and a local sand blaster were employed to reline the tank.

Work was accomplished in 7 days during an outage.

After grit blast, it was found that excessive pitting on the tank bottom had occurred, and a polyester reinforced rebuild system was employed to restore tank integrity.

OUR MISSION IS TO PROVIDE HIGHLY TECHNICAL AND  
RELIABLE SERVICE THROUGH OUR ESTABLISHED NETWORK  
OF AFFILIATED VENDORS AND STRATEGIC PARTNERS.

### Pumpcoat, Inc.

PO Box 1109

Mashpee, MA 02649

[sales@pumpcoat.com](mailto:sales@pumpcoat.com)

[www.pumpcoat.com](http://www.pumpcoat.com)

1-888-312-7278 (toll-free)

1-508-540-5878 (phone)

1-508-457-1052 (fax)

~ WBE Certified ~