

# PUMPCOAT

## THE RIGHT SOLUTION TO YOUR PUMP AND COATING PROBLEMS



### **CASE HISTORY 006 - REPLACEMENT SALT WATER PUMP BRONZE GLAND**

1) **Problem:**

Power plant in New England needed to replace bronze salt water pump gland.

2) **Circumstances prior to failure:**

No parts were available from stock room.

3) **Pumpcoat Solution**

Pumpcoat repairnet vendor manufactured pattern and new gland from worn sample. Delivery was better than the OEM and a cost savings was realized by the customer.

---

OUR MISSION IS TO PROVIDE HIGHLY TECHNICAL AND  
RELIABLE SERVICE THROUGH OUR ESTABLISHED NETWORK  
OF AFFILIATED VENDORS AND STRATEGIC PARTNERS.

---

### **Pumpcoat, Inc.**

PO Box 1109

Mashpee, MA 02649

[sales@pumpcoat.com](mailto:sales@pumpcoat.com)

[www.pumpcoat.com](http://www.pumpcoat.com)

**1-888-312-7278 (toll-free)**

1-508-540-5878 (phone)

1-508-457-1052 (fax)

~ WBE Certified ~