

PUMPCOAT

THE RIGHT SOLUTION TO YOUR PUMP AND COATING PROBLEMS



CASE HISTORY 001 - SPECIAL SHAFT SLEEVE FOR HEAVY OIL PUMP AT POWER PLANT IN NEW ENGLAND

1) Problem:

Power plant in New England needed to install mechanical seal for a heavy oil pump, but set screws wouldn't fit on the pump shaft sleeve. The set screws landed on a shaft sleeve shoulder.

2) Circumstances prior to failure:

Mechanical seal set screws were not fitting on the pump shafts sleeve. The pump shaft sleeve was too short. It needed to be longer.

3) Pumpcoat Solution

Pumpcoat designed and our vendor manufactured a special shaft sleeve customized for the pump. The customer was then able to install the mechanical seal.

OUR MISSION IS TO PROVIDE HIGHLY TECHNICAL AND
RELIABLE SERVICE THROUGH OUR ESTABLISHED NETWORK
OF AFFILIATED VENDORS AND STRATEGIC PARTNERS.

Pumpcoat, Inc.

PO Box 1109

Mashpee, MA 02649

sales@pumpcoat.com

www.pumpcoat.com

1-888-312-7278 (toll-free)

1-508-540-5878 (phone)

1-508-457-1052 (fax)

~ WBE Certified ~