



PUMPCOAT

THE RIGHT SOLUTION TO YOUR PUMP AND COATING PROBLEMS



CASE HISTORY 011 - CHILLER CONDENSER COATING

1) **Problem:**

Building in Boston found excessive corrosion of condenser.

2) **Circumstances prior to failure:**

Previously uncoated tube sheet and water box were in need of epoxy coating.

3) **Pumpcoat Solution**

Pumpcoat provided grit blast, dust collection and coating of tube sheets, waterboxes, division plates and heads.

OUR MISSION IS TO PROVIDE HIGHLY TECHNICAL AND
RELIABLE SERVICE THROUGH OUR ESTABLISHED NETWORK
OF AFFILIATED VENDORS AND STRATEGIC PARTNERS.

Pumpcoat, Inc.

PO Box 1109

Mashpee, MA 02649

sales@pumpcoat.com

www.pumpcoat.com

1-888-312-7278 (toll-free)

1-508-540-5878 (phone)

1-508-457-1052 (fax)

~ WBE Certified ~