



PUMPCOAT

THE RIGHT SOLUTION TO YOUR PUMP AND COATING PROBLEMS



CASE HISTORY 015 - BLOW DOWN TANK REPAIR

1) **Problem:**

Blow down tank had excessive pitting

2) **Circumstances prior to failure:**

Customer scheduled repair and coating of blow down tank. After grit blast , tank bottom was found to have excessive pitting and pin holes.

3) **Pumpcoat Solution**

Pumpcoat provided material and a service supervisor to work with the customers personnel

to install a reinforced epoxy liner during the customer outage.

OUR MISSION IS TO PROVIDE HIGHLY TECHNICAL AND
RELIABLE SERVICE THROUGH OUR ESTABLISHED NETWORK
OF AFFILIATED VENDORS AND STRATEGIC PARTNERS.

Pumpcoat, Inc.

PO Box 1109

Mashpee, MA 02649

sales@pumpcoat.com

www.pumpcoat.com

1-888-312-7278 (toll-free)

1-508-540-5878 (phone)

1-508-457-1052 (fax)

~ WBE Certified ~