

# PUMPCOAT

## THE RIGHT SOLUTION TO YOUR PUMP AND COATING PROBLEMS



### CASE HISTORY 016 - BROKE CHEST AGITATOR PACKING

1) **Problem:**

Customer unhappy with packing life.

2) **Circumstances prior to failure:**

Shaft sleeve and packing life were too short.

3) **Pumpcoat Solution**

Pumpcoat provided Slade packing which improved life of unit on old sleeve.

---

OUR MISSION IS TO PROVIDE HIGHLY TECHNICAL AND  
RELIABLE SERVICE THROUGH OUR ESTABLISHED NETWORK  
OF AFFILIATED VENDORS AND STRATEGIC PARTNERS.

---

### **Pumpcoat, Inc.**

PO Box 1109

Mashpee, MA 02649

[sales@pumpcoat.com](mailto:sales@pumpcoat.com)

[www.pumpcoat.com](http://www.pumpcoat.com)

**1-888-312-7278 (toll-free)**

1-508-540-5878 (phone)

1-508-457-1052 (fax)

~ WBE Certified ~