



PUMPCOAT

THE RIGHT SOLUTION TO YOUR PUMP AND COATING PROBLEMS



CASE HISTORY 020 - MEZANINE FLOOR

1) **Problem:**

Mezanine floor leaked salt water

2) **Circumstances prior to failure:**

Electrical cable trays under a mezanine floor were wetted by leaking salt water

3) **Pumpcoat Solution**

Pumpcoat contractors installed an epoxy floor and containment area to confine leakage

OUR MISSION IS TO PROVIDE HIGHLY TECHNICAL AND
RELIABLE SERVICE THROUGH OUR ESTABLISHED NETWORK
OF AFFILIATED VENDORS AND STRATEGIC PARTNERS.

Pumpcoat, Inc.

PO Box 1109

Mashpee, MA 02649

sales@pumpcoat.com

www.pumpcoat.com

1-888-312-7278 (toll-free)

1-508-540-5878 (phone)

1-508-457-1052 (fax)

~ WBE Certified ~