

PUMPCOAT

THE RIGHT SOLUTION TO YOUR PUMP AND COATING PROBLEMS

CASE HISTORY 008 - REPLACEMENT VERTICAL PUMP BACK CASING



1) **Problem:**

Septic sump pump cast iron back case was in need of replacement.

2) **Circumstances prior to failure:**

No part was available from stock room.

3) **Pumpcoat Solution**

Pumpcoat repairnet vendor manufactured replacement part or fabricated steel in 2 weeks. A cost savings and better delivery were realized over the OEM's distributor.

OUR MISSION IS TO PROVIDE HIGHLY TECHNICAL AND
RELIABLE SERVICE THROUGH OUR ESTABLISHED NETWORK
OF AFFILIATED VENDORS AND STRATEGIC PARTNERS.

Pumpcoat, Inc.

PO Box 1109

Mashpee, MA 02649

sales@pumpcoat.com

www.pumpcoat.com

1-888-312-7278 (toll-free)

1-508-540-5878 (phone)

1-508-457-1052 (fax)

~ WBE Certified ~